

AERONAUTICAL INFORMATION CIRCULAR - MOÇAMBIQUE
INSTITUTO DE AVIAÇÃO CIVIL DE MOÇAMBIQUE
DIRECÇÃO DOS SERVIÇOS DE NAVEGAÇÃO AÉREA
AERONAUTICAL INFORMATION SERVICE

Tel: (258) 21-465416
Fax: (258) 21-465415
AFTN: FQHQYSYX
iacm@tvcabo.co.mz
www.iacm.gov.mz

ALAMEDA DO AEROPORTO
Caixa Postal, 227 - Maputo



AIC - International
30/12
10 October

PROCEDURES

DETERMINING CONTINUED COMPETENCY OF AIR TRAFFIC CONTROLLERS ON NEW EQUIPMENT AND PROCEDURES

1. AUTHORITY

1.1 This circular is issued by the Executive Chairman of the Instituto de Aviação Civil de Moçambique (IACM) in pursuance of powers vested in him under Article 31 of Law N^o 21/2009 of 21 September and Article 12 of Resolution 19/2011 of 30 November.

2. PURPOSE

2.1 This Advisory Circular (AC) provides guidance on the procedures to be developed by the ANSP for determining continued competency of Air Traffic Controllers on new equipment and procedures.

3. REFERENCES

3.1. ICAO Doc 4444 PANS - ATM

4. AIM

4.1. The need for the ANSP to have these procedures in place for ATC Staff is to ensure that service provision is appropriate and adequate for maintaining an acceptable level of safety.

5.0 GUIDANCE AND PROCEDURES

5.1 The ANSP shall develop procedures for determining the continued competency of Air Traffic Controllers on new equipment and procedures.


5.2 In developing these procedures, the ANSP shall take into consideration the following provisions:

- a) Controller competency is maintained by adequate and appropriate refresher training, including the handling of aircraft emergencies and operations under conditions with failed and degraded facilities and systems;
- b) Controllers, where the ATC unit/control sector is staffed by teams, are provided with relevant and adequate training in order to ensure efficient teamwork;
- c) The implementation of new or amended procedures, and new or updated communications, surveillance and other safety significant systems and equipment is preceded by appropriate training and instruction;
- d) Controller competency in the English language is satisfactory in relation to providing ATS to air traffic; and
- e) Standard phraseology is used.

5.3 The developed procedures shall be applicable when one or more of the following circumstances prevail:-

- a) Changes in existing facilities and equipment at the operating positions;
- b) New equipment that may necessitate complete renewal of operations and equipment rooms or even new ATS units or centres;
- c) Re-organization of the airspace;
- d) Introduction of new procedures or revision of existing procedures

EXECUTIVE CHAIRMAN



Afonso Sande Cuinhane
Instituto de Aviação Civil de Moçambique